



CORYLUS ENVIRONMENTAL

# New Forest Wetland Monitoring Review Survey Report

## Higher Level Stewardship Agreement The Verderers of the New Forest AG00300016



March, 2020



Department  
for Environment  
Food & Rural Affairs



The European Agricultural  
Fund for Rural Development:  
Europe investing in rural areas



This project has been funded under the Rural Development Programme for England

### Copyright

This report has been prepared for and funded by The Verderers of the New Forest Higher Level Stewardship Agreement AG00300016. The HLS partners shall have the sole right to publish the report and results of the survey, with an appropriate acknowledgement of the work or material contributed by the Contractor.

This report should be cited as: J Smith, 2020. New Forest **Wetland Monitoring Review** Report. Higher Level Stewardship Agreement The Verderers of the New Forest AG00300016.

This report has been prepared on behalf of Forestry England, as part of The Verderers of the New Forest Higher Level Stewardship Agreement. All data used in the analysis has been supplied by Forestry England, solely for the purposes of informing the New Forest Wetland Monitoring Review.

Report Author:

Jane Smith MSc, MA(Hons), MCIEEM, MCIWEM, C.WEM  
Corylus Environmental Ltd  
The Old Coach House  
Verwood  
Dorset  
BH31 6HB

Cover Photo: Mike Read – Wootton Phase 1 (post restoration) fixed point photograph

# NEW FOREST WETLAND MONITORING REVIEW

## Contents

- 1 Introduction
2. Restoration of channel/floodplain features
  - 2.1 Background
  - 2.2 Restoration Objectives
  - 2.3 HLS Monitoring Sites
  - 2.4 Methodology
  - 2.5 Analysis & Discussion of Results
    - 2.5.1 Index 1 – Flow Types
    - 2.5.2 Index 2 – Flow Strength Types
    - 2.5.3 Index 3,4,5,6 & 7 – Bed Material Types
    - 2.5.4 Index 8 – Channel physical habitat complexity
    - 2.5.5 Index 9 to 14
  - 2.6 Conclusions
3. Restoration of Hydrological Function and Reconnection with the Floodplain
  - 3.1 Background
  - 3.2 Restoration Objectives
  - 3.3 HLS Monitoring Sites
  - 3.4 Methodology
  - 3.5 Analysis & Discussion of Results
    - 3.5.1 Wootton Water Level Analysis
    - 3.5.2 Timelapse Camera Footage - Wootton
    - 3.5.3 Pondhead – Water Level Data Analysis
    - 3.5.4 Timelapse Camera Footage - Pondhead
    - 3.5.5 Analysis of timelapse camera footage across the New Forest streams
    - 3.5.6 Wootton Phase 1- Camera 1
    - 3.5.7 Latchmore Catchment – Amberwood and Studley Wood/Claypits
  - 3.6 Conclusions
4. Water Quality
  - 4.1 Background
  - 4.2 Restoration Objectives
  - 4.3 HLS Monitoring Sites
  - 4.4 Methodology
  - 4.5 Analysis & Discussion of Results
  - 4.6 Conclusions
5. Macro-Invertebrate Monitoring
  - 5.1 Background
  - 5.2 Restoration Objectives
  - 5.3 HLS Monitoring Sites
  - 5.4 Methodology

- 5.4.1 Formal Surveys (BUG)
- 5.4.2 Riverfly
- 5.5 Analysis & Discussion of Results
- 5.6 Conclusions
- 6. Fish Monitoring
  - 6.1 Background
  - 6.2 Restoration Objectives
  - 6.3 HLS Monitoring Sites
  - 6.4 Fish Monitoring & Methodology
  - 6.5 Analysis & Discussion of Results
    - 6.5.1 Fish Species
    - 6.5.2 Population Response
    - 6.5.3 Trout Classification
    - 6.5.4 Redd Counts
    - 6.5.5 Fish population –age/size distribution
  - 6.6 Conclusions
- 7. Vegetation
  - 7.1 Background
  - 7.2 Restoration Objectives
  - 7.3 HLS Monitoring Sites
  - 7.4 Fish Monitoring & Methodology
  - 7.5 Analysis & Discussion of Results
  - 7.6 Wootton Vegetation Recovery – July 2017 to August 2019
  - 7.7 Conclusion
- 8. References